



Congratulations!

You have chosen to protect your eyes with SWORKE® performance safety eye protectors. Every piece of SWORKE® eyewear was conceived in a vortex of artistry, design expression and protection. Your SWORKE® eyewear lives and breathes engineering perfection. It was designed to protect your eyes, to be comfortable to wear, to improve your life. Your SWORKE® eyewear will help you to move mountains, to push limits and break boundaries.

SWORKE.com

Stamp of Authorized SWORKE® Optical Outlet or Retail Shop, if applicable:

SWORKE® is a registered trademark of PDS International Pte Ltd.

SWORKE® LIMITED WARRANTY POLICY

SWORKE® eye protectors are warranted by SWORKE® for a period of no more than one (1) year from date of purchase against manufacturer's defects or breakage due to material or workmanship defects. The warranty is valid only to the original purchaser with an original proof of purchase from SWORKE®, an Authorized SWORKE® Optical Outlet or Authorized SWORKE® Retail Shop, clearly showing the purchase date. Alteration, modification, misuse or abuse of the product, or installation of non-SWORKE®-approved lenses will void this warranty. SWORKE®'s warranty does not cover scratched lenses, wear and tear, damage caused by cleaning agents or any damage caused by conditions beyond its control including but not limited to, acts of God and/or any other cause beyond reasonable control of SWORKE®. The customer's exclusive remedy for a breach of warranty will be the repair or replacement of the defective product as determined by SWORKE®.

ATTENTION! YOUR SWORKE® WARRANTY IS ONLY VALID WITH A PROOF OF PURCHASE

CARE

To maintain optimal performance, do not rest your lenses against any hard or abrasive surface. Do not leave the eyewear exposed to direct sunlight under high temperatures, such as on an automobile dashboard, or window sill, as this may damage your frame and its components. Your case and microfiber cleaning cloth or pouch have been designed to protect your eyewear during transport and storage. Always be sure to keep the lenses free of dust, grime, oils, and debris before storing your SWORKE® eyewear. Following these simple steps will ensure that your SWORKE® eyewear is always ready for use whenever you need it.

CLEAN

Clean your lenses carefully. First, blow off any particles on the lens surface. Wash with mild soap and water. Wipe dry with a soft cotton or professional cleaning cloth. Do not use paper towels, other wood fiber paper products, abrasive cleaners, alkaline cleaners, or other abrasive compounds or solvents. Do not dry clean your lens. For optimal clarity and long-lasting quality, please wipe your lenses with a SWORKE® microfiber cleaning cloth or pouch.

QUALITY STANDARDS

Your SWORKE® eye protector has been tested according to ANSI/ISEA Z87.1-2010 standards for high mass and velocity impact resistance* and/or EN166 standards for low energy impact*, 99.9% UV protection against harmful UVA and UVB rays, and optical quality. These impact-resistant polycarbonate lenses are certified to ANSI Z80.1 Class 1 optical quality. All lenses are hard-coated for scratch resistance and anti-fog capabilities†.

*As indicated on the eyewear frame.

†For selected models and/or lenses only; please check with SWORKE® or any Authorized SWORKE® Optical Outlets or Retail Shops for more information.

▲ ATTENTION! READ THIS WARNING!

For your safety, ensure that your SWORKE® eyewear is fitted securely at all times. Always examine your eyewear before use and replace it immediately if there are signs of pits, scratches or damage. Ensure that you are using the proper eyewear suitable for your intended purposes. SWORKE® eyewear only provide limited protection. They are not designed to provide protection in industrial environments and are not substitutes for machine guards and other engineering controls. The frame and lenses of SWORKE® eyewear are not unbreakable. Exposure to or contact with chemical vapors or liquids may cause surface cracks and/or other damage. Tinted lenses offer limited protection against sun glare and other light sources. They are not designed to protect you against optical hazards during welding, brazing, or furnace operations. Do not modify this product. Do not use this product for protection against laser light, molten metal, gases vapors, mists, smoke and fine particles. Using your SWORKE® eyewear for activities including but not limited to the aforementioned purposes, paintball or simulated war game activities will void the SWORKE® warranty policy. SWORKE® shall not be liable or responsible for any loss, damage, or liability, direct, indirect, incidental, special, or consequential, arising out of sale, use, or misuse, or the inability to use products by the user.

HANDLE A WARRANTY CLAIM

Contact the Authorized SWORKE® Optical Outlet or Authorized SWORKE® Retail Shop from which your purchase was made, or any Authorized SWORKE® Service Center or SWORKE® for assistance. Visit any Authorized SWORKE® Service Center or SWORKE® with your product and proof of purchase. If you are unable to visit our premises in person, you may send your product to us by post. To avoid any damage during transit, please pack your product in its original case and packaging. As it is your responsibility to ensure that your product reaches SWORKE® safely, you are advised to obtain a tracking number or proof of postage, or insure your parcel. SWORKE® will not be responsible for any damage caused by improper packaging or loss in transit. (For a full listing of Authorized SWORKE® Optical Outlets, Retail Shops, Service Centers and other contact information, please visit sworke.com or sworke.com.sg or email us at info@sworke.com.)